

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME *Skanna* Rpt. *Apr.* No. *18121*
June " *98640*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine *Triple Expansion & LP turbine with D.R. gearing & hydraulic coupling.*

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of approved type }

No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+LMC 3.41*

L.S.
17/3/41



© 2021

Lloyd's Register Foundation

01548 01546-0145

13

U
S
T
F
B
P
S
D
C
S
E
D
N
N

NO. 1871
R.M.
VESSEL'S NAME

Handwritten signature

Type of engine

Handwritten notes

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is admitted she is eligible to be classed.



© 2021

Lloyd's Register
Foundation

Where fitted.	Length.	Water capacity.	Where fitted.	Length.	Water capacity.
	Feet.	Tons.		Feet.	Tons.