

REPORT of SURVEY for REPAIRS, &c.

4078

No. 4048 Date of Writing Report April 30 1890 Port of Aberdeen Received in London Office, THURS 1 MAY 1890
 No. in Reg. Book. 29 Survey held at Aberdeen Date, First Survey Apr. 26 Last Survey Apr. 30 1890
 on the S.S. "Earl of Aberdeen" (No. of Visits 2) Master G. M. Bain YEAR. MONTH.

TONNAGE:—
 NET 326 Built at Aberdeen By whom Hall Russell & Co When 1889
 GROSS 434 Owners Abn, Nwe, Hull, S. N. Co. Lim Port belonging to Aberdeen
 UNDER DK. 573 Owner's Address
 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock dry dk Name of Dock Abn dry dk Destined Voyage Coasting
 Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 4019 Port Abn. Classed _____
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 in Summer / _____ ft. 9 1/2 ins.
 as painted on Ship } in Winter / _____ ft. // ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Sighting bottom

The vessel placed in the above dry dock and the bottom examined and found in good condition and afterwards repainted


PRESENT CONDITION OF THE			
Decks <u>Good</u>	Plank (Bottom) & Counter <u>Good</u>	Ceiling <u>Good</u>	Boats <u>Good</u>
Waterways "	Treenails or Rivets "	Rudder "	Masts, Yards, &c. "
Comings "	Breasthooks and Stemson "	Windlass & Capstan "	Condition, how ascertained <u>found</u>
Up'r Dk. Beams & Fastenings "	Transoms, Pointers, & Crutches "	Pumps "	Sails "
Low'r Dk. Beams & Fastenings "	Timbers of Frame at the opening "	Cement (if Iron Ship) "	Anchors No. of <u>3/18/82k</u>
Planksheers "	Ditto ditto at other places "	Caulk'ng of Bot'm, D'k, & Watrways "	Cables "
Sheerstrakes "	Keelsons "	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps "
Topsides "	Clamps & Shelves "	When put on	Standing & Running Rigging "
Wales "			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :
This vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to be recorded 4-90 in the Register Book

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

G. L. Hindmarsh
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 2 MAY 1890
 Character assigned 100 A 1



ABN 10-0012

State if a Report is also sent or if not whether, and when, the vessel was surveyed.

Insert Character precisely as in Register Book.