

REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

No. 4265 Date of Writing Report July 31 1891 Port of Aberdeen
 No. in Reg. Book. 90 Survey held at Murray Date, First Survey July 30 Last Survey July 30 1891
 on the S.S. "Barbaras" Master Cooper (No. of Visits) 1 YEAR MONTH.

TONNAGE:—
 NET 64 Built at Aberdeen By whom H. Jarvis When 1888 5
 GROSS 93 Owners H. R. Aiken Port belonging to Kirkcaldy

UNDER DK. 91 Owners' Address (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Slipway Name of Dock J. Guthrie & Co's Slipway Destined Voyage Coasting
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 8009 Port Aberdeen S. No 6 8. 88 9 A. 5. 90
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship) in Winter ft. ins.
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Sighting bottom
The vessel placed on the above slipway and the bottom examined and found in good condition and afterwards recoated


PRESENT CONDITION OF THE							
Decks	<u>Good</u>	Plank (Bottom) & Counter	<u>Good</u>	Ceiling	<u>Good</u>	Boats	<u>Good</u>
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained	<u>from deck</u>
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors	No. of <u>2 No. 15. 1 K</u>
Planksheers	"	Ditto ditto at other places	"	Caulk'ng of Bot'm, D'k, & Watrways	"	Cables	"
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Topsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights		Coal Bunker, Openings, Lids, &c		Scuppers		Cargo & Main Hatchways	

General Observations, Opinion as to Class, Recommendation, &c. :
This vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to be noted 7-91 in the Register Book

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	18
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	Received by me,
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute TUES. 4 AUG 1891
 Character assigned 9 A 1 for Coasting purposes

G. L. Hindmarsh
 Surveyor to Lloyd's Register of British & Foreign Shipping.



State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent.

Insert Character precisely as in Register Book.