

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report July 24 1894 When handed in at Local Office July 24 1894 Port of Aberdeen
No. in Reg. Book. 393 Survey held at Aberdeen Date, First Survey June 20 Last Survey July 23 1894
on the Wood, Iron or Steel S.S. North Star (No. of Visits 4) Master N. Cook

TONNAGE:— Built at Aberdeen By whom J. Guthrie Sons & Co. When 1883 YEAR. MONTH.
GROSS 126 Owners W. Pyper Port belonging to Aberdeen
UNDER DK. 115 Owners' Address
NET 46 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Abn dry dk Destined Voyage Trawling
WB=DBa tons; f tons; uE&B tons; CellDB tons; }
FRT tons; APT tons; MT tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey, No. 4699 Port Abn

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Sighting bottom

The Vessel placed in the above dry dock, the bottom examined and found in good condition, and afterwards repainted.
The boiler casing worn through for a distance of two feet; this has now been efficiently repaired

SUMMARY OF DAMAGE REPAIRS:— Plates, Faird or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE			
Decks <u>Good</u>	Transoms, Pointers, & Crutches <u>Good</u>	Copper, or Y.M. (State if on Fell.)	Hatches <u>Good</u>
Waterways	Timbers of Frame at the openings	When put on, Month Year	Boats
Coamings	Ditto ditto at other places	Rudder <u>Good</u>	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Windlass & Capstan	Condition, how ascertained <u>from dk</u>
Low'r Dk. Beams & Fastenings	Clamps, Shelves & Stringers	Pumps	Sails
Plating	Salting (State if examined.)	Engine Room Skylights	Equipment letter
Planking	Ceiling	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of <u>2 B/S/K</u>
Ironails or Rivets	Cement or Asphalt (State which.)	Scuppers	Cables (State if now ranged) <u>No</u>
Breasthooks & Stemson	Tanks (State if now tested.)	Cargo & Main H'tchw'ys	„ length size
	Caulking of Bot'm, D'k, & Wat'r'w'ys		„ Rule length size
			Hawsers & Warps <u>Good</u>
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 9,91,” or “to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c.”

This vessel so far as seen is now in good and efficient condition, and eligible in my opinion to remain as classed, and to be noted 7. 94 in the Register Book

Office Fee (if chargeable) per Sec. 11, Sec. 27 £ : : Fees applied for, 18.
Survey Fee (per Section 28) £ : : Received by me, 18.
Special Damage or Repair Fee (if any) (per Sec. 28.) £ : :
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
Is Certificate now required?

Committee's Minute
Character assigned
FRIDAY 27 JUL 1894
100A1 Stm Trawler
BSy. 94
Lloyd's Register Foundation
ABN 12-0007