

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 21<sup>st</sup> Nov. 1898 When handed in at Local Office 21<sup>st</sup> Nov. 1898 Port of AberdeenNo. in Survey held at Aberdeen Date, First Survey 21<sup>st</sup> Nov. Last Survey 21<sup>st</sup> Nov. 1898

Reg. Book. on the Wood, Iron or Steel S. K. "Faith." Master M. D. 91-91.

TONNAGE:—

GROSS 135-

UNDER DEK 29-

NET 46-

Built at Kinghorn By whom J. Scott &amp; Co.

Owners S. Williamson (J. D. Signor) Port belonging to Kirkcaldy

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? D. Dk. Name of Dock Abn. D. Dk. Destined Voyage Fishing.

WB=Cell D Bor DBa feet; uE&B feet; J feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5798 Port Abn

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and, besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &amp;c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

CHARACTER	For Special Survey	Date of last Survey and of Periodical Surveys	Machinery and Boiler Survey (including date of N.B., if any).
100	Abn.	10-98	10-98
100	Abn.	10-98	10-98

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

The bottom seen cleaned &amp; painted &amp; found satisfactory.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks	Good.	Stringers	Good.	Engine Room Skylights	Good.	Boats	Good.
Caulking of Decks	"	Inner Bottom Plating	"	Coal Bunkers, Open'gs, Lids, &c.	"	Masts, Yards, &c.	"
Waterways	"	State if Tanks now tested	Good	Scuppers	"	Condition, how ascertained	from deck
Coamings	"	Bulkheads	"	Cargo Hatchways	"	(State if wedges removed)	no.
Beams & Fastenings	"	Ceiling	"	Hatches	"	Sails	Said to be good.
Outside Plating	"	Cement or Asphalt (State which.)	Not Seen.	Planking of Wood Vessels	"	Equipment letter	"
Caulking of ditto	"	Rudder	Good.	Treenails	ditto	Anchors, No. of	353.
Rivets	"	Windlass	"	Breasthooks & Stemson	ditto	Cables (State if now ranged)	no.
Breasthooks & Stemson	Not Seen.	Have Pumps now been examined and found efficient?	Not Now.	Transoms, Pointers, & Crutches	ditto	Length (on board)	size
Transoms	Good.	Have Sluice Valves now been examined and found efficient?	Do.	Timbers of Frame at openings	ditto	Rule length (per Table 22)	size
Frames	"	Have Watertight Doors now been examined and found efficient?	Do.	Ditto ditto at other places	ditto	Hawsers & Warps	Good.
Reverse Frames	"			Stringers, Clamps & Shells	ditto	Standing & Running Rigging	"
Floors	"			Salting (State if examined.)	ditto		
Keelsons	"			Copper, or Y.M. (State if on Felt.)	ditto		
		Dblg. Plates under Sounding Pipes	Do.	When put on, Month	Year		

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &amp;c."

This vessel appears to be in good condition, eligible in my opinion to remain as classed, with fresh record of 11-98 in the Reg. Bk.

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 28)

Special Damage or Repair Fee (if any) (per Sec. 28.)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

Received by me,

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

Committee's Minute

Character assigned

TUES. 29 NOV 1898

1000A1 Steam Trawler

BS 11, 98



© 2019

Lloyd's Register Foundation

ABN 15-0377