

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *April 15 1899* When handed in at Local Office *April 15 1899* Port of *Aberdeen*  
No. in Survey held at *Aberdeen* Date, First Survey *April 12 1899* Last Survey *April 12 1899*  
Reg. Book. *40* on the Wood, Iron or Steel *S.S. "East Wind"* (No. of Visits *one*) Master *R. Craig*

TONNAGE:— Built at *Aberdeen* By whom *W. Garner* When *1895-8*  
GROSS *118* Owners *R. Craig* Port belonging to *Aberdeen*  
UNDER DEK *105* Owners' Address  
NET *10* (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? *at* Name of Dock *Shells' slip* Destined Voyage *Fishing*  
WB=CellDBorDBa feet; uE&B feet; J feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons. }  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.	Years Assigned and expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<i>+9A - For fishing purposes</i>	<i>+98 3.99</i>	<i>+LMC 9.95</i>
		<i>+NE&amp;B 9.94</i>
		<i>refitted 95</i>

Last Report, No. *35971* Port *Dunc*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

*Condition*  
*The bottom, sea connections, & propeller fastenings examined & found in good order.*

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks <i>Good</i>	Stringers <i>✓</i>	Engine Room Skylights <i>good</i>	Boats <i>good</i>
Caulking of Decks <i>✓</i>	Inner Bottom Plating <i>✓</i>	Coal Bunkers, Open'gs, Lids, &c. <i>✓</i>	Masts, Yards, &c. <i>✓</i>
Waterways <i>✓</i>	State if Tanks now tested <i>✓</i>	Scuppers <i>✓</i>	Condition, how ascertained <i>from all</i>
Coamings <i>✓</i>	Bulkheads <i>good</i>	Cargo Hatchways <i>✓</i>	(State if wedges removed <i>NO</i> )
Beams & Fastenings <i>✓</i>	Ceiling <i>✓</i>	Hatches <i>✓</i>	Sails <i>raid &amp; regood</i>
Outside Plating <i>✓</i>	Cement or Asphalt <i>✓</i>	Planking of Wood Vessels <i>✓</i>	Equipment letter <i>✓</i>
Caulking of ditto <i>✓</i>	(State which.) <i>✓</i>	Treenails ditto <i>none</i>	Anchors, No. of <i>1/3</i>
Rivets <i>✓</i>	Rudder <i>✓</i>	Breasthooks & Stemson ditto <i>good</i>	Cables (State if now ranged) <i>no</i>
Breasthooks & Crutches <i>✓</i>	Windlass <i>✓</i>	Transoms, Pointers, & Crutches ditto <i>✓</i>	length (on board) size <i>✓</i>
Transoms <i>✓</i>	Have Pumps now been examined and found efficient? <i>no</i>	Timbers of Frame at openings ditto <i>✓</i>	Rule length (per Table 22) size <i>✓</i>
Frames <i>not seen</i>	Have Sluice Valves now been examined and found efficient? <i>no</i>	Ditto ditto at other places ditto <i>✓</i>	Hawsers & Warps <i>good</i>
Reverse Frames <i>✓</i>	Have Watertight Doors now been examined and found efficient? <i>none</i>	Stringers, Clamps & Shelves ditto <i>✓</i>	Standing & Running Rigging <i>✓</i>
Floors <i>✓</i>	Have Watertight Doors now been examined and found efficient? <i>none</i>	Salting (State if examined.) ditto <i>✓</i>	
Keelsons <i>✓</i>	Dbing. Plates under Sounding Pipes <i>none</i>	Copper, or Y.M. (State if on felt.) ditto <i>none</i>	
		When put on, Month <i>✓</i> Year <i>✓</i>	

## General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

*This vessel appears to be in good condition, eligible in my opinion to remain as classed with fresh record of 4.99 in the Reg. Book—*

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,	
Survey Fee (per Section 28)	£ <i>none</i>		18.
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,	
Travelling Expenses (if chargeable)	£		18.
Second Surveyor's Fee (if any)	£		

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUES. 18 APL 1899

ES. 6 JUN 1899

FRI. 10 NOV 1899

Character assigned

*9A - for fishing purposes*

FRI. 1 DEC 1899



© 2019

Lloyd's Register Foundation

ABN 16-0090