

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *Dec 21st 99* When handed in at Local Office *Dec 21st 99* Port of *Aberdeen*
No. in Survey held at *Aberdeen* Date, First Survey *Dec 20th 99* Last Survey *Dec 20th 1899*
Reg. Book. *1365* on the *Wood, Iron or Steel* *P.P. "Swallow"* (No. of Visits *one*) Master *D. Dawson*

TONNAGE:— Built at *Greenock* By whom *Carlis Co. (Lim)* When *1893* - *5*
GROSS *134* Owners *Disraeli Fishing Co. Ltd (J. Davidson Mgr)* Port belonging to *Aberdeen*
UNDER DEK. *129* Owners' Address
NET *38* (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? *SD* Name of Dock *Aberdeen* Destined Voyage *Fishing*
WB=CellDBorDBa feet; uE&B feet; J feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. *198* Port *Greenock*
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. for Special Survey and of Date of last Survey and of Periodical Surveys. Years Assigned expired. Machinery and Boiler Surveys (including date of N.B., if any).
+100A1. Skin Plank +MC 7,97
8,99 *B, 6,99*
\$\$ 3ms No 1-99

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition*
The bottom sea connections & propeller fastenings examined & found in order.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblng. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Treenails	Breasthooks & Stenson	Transoms, Pointers, & Crutches ditto	Timbers of Frame at openings ditto	Ditto ditto at other places ditto	Stringers, Clamps & Sheels ditto	Salting (State if examined.)	Copper, or Y.M. (State if on Felt.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board) size	Rule length (per Table 22) size	Hawsers & Warps	Standing & Running Rigging
<i>good</i>	<i>good</i>	<i>none</i>	<i>✓</i>	<i>good</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>✓</i>	<i>good</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>ditto</i>	<i>ditto</i>	<i>ditto</i>	<i>ditto</i>	<i>ditto</i>	<i>ditto</i>	<i>ditto</i>	<i>ditto</i>	<i>Year</i>	<i>good</i>	<i>✓</i>	<i>from dk</i>	<i>good</i>	<i>✓</i>	<i>3 B</i>	<i>good</i>	<i>✓</i>	<i>✓</i>	<i>good</i>	<i>✓</i>	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and pEND98, &c."
This vessel appears to be in good condition eligible in my opinion to remain as classed with fresh record of 12-99 in the Reg. Book.

Office Fee (if chargeable) per Scale II., Sec. 27£ : : Fees applied for, : :
Survey Fee (per Section 29)£ *none* : : : : 18.....
Special Damage or Repair Fee (if any)£ : : : : Received by me, : :
(per Sec. 28.) : : : : : : : : : :
Travelling Expenses (if chargeable)£ : : : : 18.....
Second Surveyor's Fee (if any)£ : : : : : : : : : :
Committee's Minute *WED. 27 DEC 1899*
Character assigned *✓* *100A1 Skin. Frayler*

Committee's Minute *WED. 27 DEC 1899*
Character assigned *✓* *100A1 Skin. Frayler*
Lloyd's Register Foundation
© 2019
ABN16-0406

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to