

ANNUAL SURVEYS.

and change of Owner,

920

No. 920 Survey held at Peterhead Date 3^d of August 1842
 on the Brig Active Master Alexander Neutchen
 Tonnage 260 Built at Aberdeen Peterhead When built 1834
 By whom built James Geddes Owners James Gule Junr
 Port belonging to Peterhead Destined Voyage by Mull of Galloway
 If Surveyed Afloat or in Dry Dock Surveyed in the Dry Dock

In the Register Book
 Original Survey, No. 59 Port of Liverpool 1840 Classed A.T.
Peterhead 6, Nov. 1906, No. 3568
 The Surveyor is required to state the present Condition of the undormentioned articles are all in good condition as far as can be seen

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>25 Bower / 1 Stream / 1 Hedge</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>in 1842, with paper under</u>

General Observations and Opinion, *Has now been thoroughly overhauled caulked, Recoppered with paper as required by the Instructions, under, and refitted to this date, and change of Owner, Bully equal to her present character of £1000 Received by me Wm Chiere*

Committee Minute 9th August 1842
 Character assigned A.T. 1 over 2 Copper

No. 921 Survey held at Aberdeen Date 4th of August 1842
 on the Brig Myrtle Master Robert Sutter
 Tonnage 40 Built at Aberdeen When built 1809
 By whom built William Stephen Owners William Stut
 Port belonging to Aberdeen Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock Surveyed Afloat

Original Survey, No. 802 Port of Aberdeen 4th of August 1841 Classed A.T.
544, 656, 801
 The Surveyor is required to state the present Condition of the undormentioned articles are all in good condition as far as can be seen

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>2 Bower / 1 Hedge</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Double</u>

General Observations and Opinion, *Has received no particular repairs only caulking and the necessary overhaul in the Rigging and Sails, Bully equal to her present character,*

Committee Minute 9th August 1842
 Character assigned A.T. 1 over 2