

Sent to Chief Surveyor

14/3/95.

Received from Chief Surveyor

VESSEL'S NAME

St. Clair

Report

No.

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

L.L. 13/3

ST. CLAIR (s).—Wick, March 13, 1 23 p.m.—St. Clair taken off the strand safely and berthed North Quay, Wick Harbour.

C.S.R.

It is submitted the Owners should be asked to state in view of the above, at what port the vessel could be inspected by one of the Society's Surveyors with a view to the repairs being carried out to their satisfaction, and to render the vessel eligible to have her class re-instated in the Register Book.

For W. Redman.

Sr. to Owners



15.3.95

C.A.F.
15/3/95
© 2021

Lloyd's Register
Foundation

ABN24-0096