

ANNUAL SURVEYS.

Reg 7/10/1822

No. 1022 Survey held at Barruff Date May 22nd 1858
 on the Schooner Matilda Master Wm Erdig
 Tonnage 91 Built at Barruff When built 1854
 By whom built John Watson Owners John Calder
 Port belonging to Pinehorn Destined Voyage Barruff Coaster
 If Surveyed Afloat or in Dry Dock On patent Slip

73

Last Survey, No. 233 Port of Barruff Classed 7 A 1/54

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>2 Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>1 Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good where seen</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails <u>one suit Good</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>4 Good</u>
Sheerstrakes <u>Good</u>	Ceiling <u>Good</u>	Cables <u>Good</u>
Topsides <u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps <u>Good</u>
Wales <u>Good</u>	Copper <u>none</u> When put on <u></u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
This vessel has been well overhauled, including spars, rigging, sails, hawsers, crimps &c. and all necessary repairs have been completed with six new loading knees fitted to upper deck beams, & sundry extra fastenings introduced in outside planking of bottom. The pintles of rudder also refastened, &c.
 Committee's Minute 8th June 1858 W.D.O.

Character assigned 7 A 1 W.D.O.
 Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____



© 2021

Certificate (if required).

Lloyd's Register Foundation

ABN 4-0073

1852. ABN

The Vessel recaulked from keel to gunwale, including
planksheers, waterways & deck all over. The Vessel is
in a sound & efficient state fit for the conveyance of any &
perishable cargoes to & from all parts of the world, &
is eligible in my opinion to remain, A. S. As Claimed
Wm. M. L. Esq.



© 2021

Lloyd's Register
Foundation