

REPORT of SURVEY for REPAIRS.

Rev 6/8/84

in No. 2539 Survey held at Aberdeen Date, first Survey 22 Feb Last Survey 27 Feb 1877
Book. on the Agnes B Master A. Milne
Tonnage 199 built at Aberdeen When built 1856
By whom built Quirk Owners A. Milne
Port belonging to Aberdeen Destined Voyage Alicante
If Surveyed Afloat or in Dry Dock Afloat Victoria Dock
Survey, No. 2458 Port Aber Classed G A Red
AIRS, &c. Vessel caulked from metal line wall.

ent Condition of the			
s <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>	
erways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>	
ings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>See in good condition</u>	
er Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>	
er Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>by examination</u>	
ksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>	
rstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bow 1 Stern 1 Reg</u>	
sides <u>"</u>	Ceiling <u>"</u>	Cables <u>Good</u>	
les <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>	
nk (Bottom) and Counter <u>Not seen</u>	Copper <u>See below</u> When put on <u>1859</u>	Standing & Running Rigging <u>"</u>	
ine Room Skylights <u>"</u>	Caulking of <u>Good</u>		
Coal Bunker, Openings, Lids, &c. <u>"</u>	Bottom, Deck, & Waterways <u>Good</u>		
Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good</u>	

General Observations and Opinion,
This vessel appears to be in good and efficient condition eligible
in my opinion to remain as Classed A in Red

The Amount of Entry Fee.....£ : : is received by me,

Mar 14 Special..... : 10 : 6

Certificate (if required) : :

Committee's Minute 27th March 1877

Character assigned A in Red

J. W. Little



© 2019
Lloyd's Register
Foundation