

REPORT of SURVEY for REPAIRS.

2654

No. in Reg. Book. **No. 2654** Survey held at **Aberdeen** Date, first Survey **27th 6th** Last Survey **17th 2nd 1873**

on the **"Stone" Bg** Master **A. Milne**

Tonnage **199** built at **Aberdeen** When built **1855**

By whom built **J. Ruthe** Owners **A. Milne**

Port belonging to **Aberdeen** Destined Voyage **Shucka**

If Surveyed Afloat or in Dry Dock **Afloat in Victoria Dock Aberdeen**

Last Survey, No. **2593** Port **Aberdeen** Classed **9 A. 1**

REPAIRS, &c. **Renewed Chain plate bolts. Caulked part of copings.**

Present Condition of the

Decks San where seen	Treenails Good where seen	Windlass and Capstan Good
Waterways "	Breasthooks and Stemson San where seen	Pumps Afloat
Comings "	Transoms, Pointers, and Crutches "	Boats Good
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Condition, how ascertained from examination
'lanksheers "	Keelsons "	Sails Sufficient
Heerstrakes "	Clamps and Shelves "	Anchors No. of Sufficient
Topsides "	Ceiling "	Cables "
Wales "	Rudder "	Hawsers and Warps Good
Plank (Bottom) and Counter Not seen	Copper Yellow Metal When put on 1859	Standing & Running Rigging Good
Engine Room Skylights "	Caulking of San where seen	Cargo and Main Hatchways Good
Coal Bunker, Openings, Lids, &c. "	Bottom, Deck, & Waterways seen	Hatches Good
Scuppers Good		

General Observations and Opinion,

This vessel appears to be in fair condition eligible in my opinion to remain as classed A. 1.

The Amount of Entry Fee.....£ : : is received by me,

Special..... : No. : 6

Certificate (if required) : : :

Committee's Minute **18th Febr 7** 1873

Character assigned **A. 1**

J. P. W.

J. P. W.



© 2019

Lloyd's Register Foundation

A306-0117