

ANNUAL SURVEYS.

2868

Rev 23/12/74

No. in Reg. Book. **No. 2808** Survey held at **Abudeen** Date, first Survey **Dec 14** Last Survey **Dec 14** 18 **75**

on the **Elizabeth** Master **J Anderson**
Tonnage **110** Built at **Howden** When built **1844**
By whom built _____ Owners **Messrs J & P Pixie**
Port belonging to **Abudeen** Destined Voyage **Coasting**
If Surveyed Afloat or in Dry Dock **Afloat Victoria Dock Abudeen**

Last Survey, No. **2788** Port of **Abudeen** Classed **C** Years assigned **3** Character in Register Book. **S. 74**
SA 10 1 m Red
9.74

Present Condition of the Decks Good	Treenails Good	Windlass and Capstan Good
Waterways Good	Breasthooks and Stenson Good	Pumps 2 of which Good
Comings Good	Transoms, Pointers, and Crutches Good	Boats One Good
Upper Deck Beams & Fastenings Good	Timbers of the Frame at the Openings Good	Masts, Yards, &c. Good
Lower Deck Beams & Fastenings Good	Ditto ditto at other places Good	Condition, how ascertained from examination
Planksheers Good	Keelsons Good	Sails Good
Sheerstrakes Good	Clamps and Shelves Good	Anchors, No. of 2 Bars & 1 Regd
Topsides Good	Ceiling Good	Cables Good
Wales Good	Rudder Good	Hawsers and Warps Good
Plank (Bottom) and Counter Good	Copper or Y.M. When put on	Standing and Running Rigging Good
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways Good where tested	Cargo and Main Hatchways Good
Coal Bunker, Openings, Lids, &c. _____	Scuppers Good	Hatches Good

General Observations, Opinion as to Class, &c. **This vessel appears to be in good and efficient condition and is eligible in my opinion to remain as classed.**

Committee's Minute **24 Dec 1875**
Character assigned **A 1 m red**
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) **2.6** Paid **Dec 1875**

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
No. in Reg. Book. on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____	Port of _____	Classed _____	Years assigned _____	Character in Register Book. _____
Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____		
Waterways _____	Breasthooks and Stenson _____	Pumps _____		
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____		
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____		
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____		
Planksheers _____	Keelsons _____	Sails _____		
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____		
Topsides _____	Ceiling _____	Cables _____		
Wales _____	Rudder _____	Hawsers and Warps _____		
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____		
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____		
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____		

Committee's Minute **24 Dec 1875**
Character assigned **A 1 m red**
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____

