

# ANNUAL SURVEYS.

2958  
Rec 19/2/77

No. in Reg. Book. 251 No. 2958 Survey held at Aberdeen Date, first Survey Feb 16 Last Survey Feb 17 1877  
 on the Agnes Master A. Milne  
 Tonnage 191 Built at Aberdeen When built 1856  
 By whom built Duffie Owners A. Milne  
 Port belonging to Aberdeen Destined Voyage Leuchry  
 If Surveyed Afloat or in Dry Dock Afloat Victoria Dock Aberdeen

Last Survey, No. 277 Port of Ramsgate Classed 9 Years assigned 3 Character in Register Book AB in Red  
 Present Condition of the Decks Good Treenails Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Plank sheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Steel on planks When put on 1879  
 Caulking of Bottom, Deck, & Waterways Good where needed  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. This vessel appears to be in good condition and is eligible in my opinion to remain as Classed

Committee's Minute 20<sup>th</sup> February 1877  
 Character assigned AB in Red  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 10/- Paid Feb 10 1877

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned \_\_\_\_\_ Character in Register Book \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Plank sheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_

ABNG-0356

