

# ANNUAL SURVEYS.

3323  
Reg 30/12/80

No. 3323 Survey held at Peterhead Date, first Survey Dec 23 Last Survey Dec 23 18 80  
 No. in on the Promise Master W. Bant  
 Reg. Book. 400 Tonnage 50 Built at Peterhead When built 1848 5 months  
 By whom built Harvey Owners W. Bant  
 Port belonging to Peterhead Destined Voyage not fixed  
 If Surveyed Afloat or in Dry Dock Dry Dock Peterhead

Last Survey, No. 3153 Port of Aber Classed 6 Years assigned. 4.48 Character in Register Book. omitted  
 Present Condition of the Decks Good Treenails Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers Good Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Good When put on Good  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. This vessel appears on examination to be in good and efficient condition, and is eligible in my opinion to be entered in Register Book Oct 1 from 1878

Committee's Minute Friday, December 31st 1880  
 Character assigned CA 1 TRU  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 2.0 Paid Dec 28 18 80  
 Travelling expenses L 1.1.0

No.            Survey held at            Date, first Survey            Last Survey            18             
 No. in on the            Master             
 Reg. Book.            Tonnage            Built at            When built             
 By whom built            Owners             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock             
 Last Survey, No.            Port of            Classed            Years assigned.            Character in Register Book.             
 Present Condition of the Decks            Treenails             
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on             
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18             
 Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            18           

