

Report of Survey for Repairs of Engines and Boilers.

No. 306

(Received at London Office, Rec'd 18th FEB. 1884.)

No. in Reg. Book. 262 Survey held at Aberdeen Date, first Survey 31st Jan Last Survey 31 Jan 1884
on the Machinery of the S.S. "Ben Aron" (Number of Visits one)

| | | |
|--------------------------------|---|----------------------------|
| Tonnage, Gross 632 | Built at Aberdeen | When built 1875 |
| Ditto, Net 402 | Owners J & A Davidson | Port belonging to Aberdeen |
| Diameter of Cylinder 24" x 40" | Engines made by Hall Russell & Co | When made 1875 |
| Length of Stroke 30" | Boilers made by do do | When made 1875 |
| Pressure of Steam 65 lbs | If Surveyed Afloat or in Dry Dock on Hall & Co Ship | Classed 90A1 |
| Registered Horse Power 80 | (State name of Dock.) | 12-82 |
| Last Survey No. | Port B.M.S. 12, 82 | 58 Port No 2-82 |

Particulars of Repairs and Examination This vessel has been placed on the slip on account of the breaking of her screw shaft in the North Sea. A new shaft and propeller has been fitted at this time and all is again in good order.

Disputes that this vessel is eligible to remain as classed
M 187/84

General Observations, Opinion, and Recommendation:— The machinery of this vessel is again in good working order, and in my opinion eligible to remain as classed

Entry or Registering Fee... £ — : —

(per Section 27.)

Survey Fee (per Section 28) ... £ — : — received by me,

Certificate (if required) ... £ — : — 188

to be sent as per margin.

(Travelling Expenses, if any, £ —)

Committee's Minute

TUESDAY 19 FEB 1884

188

Assigned

John Sturrock

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

London & District



Lloyd's Register Foundation

ABM-0038