

# ANNUAL SURVEYS.

3548

(Received at London Office) **TUESDAY 5 AUGUST 1884**

No. 3548 Survey held at Aberdeen Date, first Survey July 29 Last Survey July 29 1884  
 No. in Reg. Book. on the Edward Austin Master Hudson  
 Tonnage { Net 45 Built at Sunderland When built 1869 3  
 { Gross 49  
 { Under Dk. 48 By whom built R. Pickersgill Owners Hudson & Co  
 Port belonging to London Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Afloat Aberdeen Society's Freeboard (if assigned) as painted on Ship

*[Handwritten signature]*

Last Survey, No. 12471 Port of Scot. Classified 10 Years assigned. 10 Character in Register Book. 10  
 Present Condition of the Decks Good MOULDED DEPTH of Ship, if not yet recorded in Register Book. 10 10 10  
 Treennails Good 10 10  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. This vessel is found on examination to be in good condition and is eligible in my opinion to remain as classed  
 Committee's Minute FRIDAY 8 AUGUST 1884  
 Character assigned Good Surveyor to Lloyd's Register of British and Foreign Shipping. J. W. Kettle  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_ (No. of Visits \_\_\_\_\_)  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 { Gross \_\_\_\_\_  
 { Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classified \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ MOULDED DEPTH of Ship, if not yet recorded in Register Book. \_\_\_\_\_  
 Treennails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_

General Observations, Opinion as to Class, &c. \_\_\_\_\_  
 Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18\_\_\_\_

Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery.) (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery.) (Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

