

# Report of Survey for Repairs, &c., of Engines & Boilers.

3723

(Received at London Office,

MONDAY 1 NOV 1886)

No. 3723-

No. in Reg. Book. 56 Survey held at Aberdeen Date, first Survey \_\_\_\_\_ Last Survey 16<sup>th</sup> Oct 1886  
 on the Machinery of the S.S. Lady Cathcart (Number of Visits 4 Year \_\_\_\_\_ Month \_\_\_\_\_)

Tonnage, Gross 648 Built at Aberdeen When built 1882-9  
 Ditto, Net 418 Owners Aberdeen Lime Coy Port belonging to Aberdeen  
 Diameter of Cylinder 24" x 42" Engines made by Blairie Bros When made 1882  
 Length of Stroke 30" Boilers made by D° D° When made 1882  
 Pressure of Steam 80 If Surveyed Afloat or in Dry Dock Hall's Slip (State name of Dock.)  
 Registered Horse Power 75 Classed 100 A1 Character in Register Book.  
 Last Survey No. 3672 Port Abr I.M.C. 10-82.

Particulars of Repairs and Examination Damage + S.S. No 1  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

From Damage -  
 The Stern tube + Tail shaft examined + found in good order.  
 In S.S. No 1  
 The crank shaft examined + found sound,  
 The Cylinders, Slides, pistons, pumps + the Engines generally examined + found in good order,  
 The Main + Donkey boilers examined + found satisfactory,  
 The Safety Valves tested under steam,

General Observations, Opinion, and Recommendation:—  
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)  
 The Machinery of this vessel is now in good order, eligible in my opinion to remain as classed + to have I.M.C. 10-86 recorded.

Office or Registration Fee (per Sec. 27)	£	:	:	} received by me, } J.H.H. 30. Oct 1886
Survey Fee (per Section 28)	£	2	2	
Special Damage Fee (per Section 28)	£	:	:	
Certificate (if required)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	

John H Heck  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUESDAY 2 NOV 1886  
 Assigned L M 10.86



Insert Character of Ship and Machinery precisely as in the Register Book.

\* Certificate to be sent to the Registrar of Shipping (The Surveyors are requested not to write on or below the space for Committee's Minute).

No. of Vessel	Name of Vessel	Class	Builder	Date of Construction	Surveyed by	Date of Survey	Remarks
3723	Albion	...	...	...	...	...	...

3723. Albion

It is submitted that this vessel  
 is eligible to have the  
 notification sent to the  
 recorder.

11/1/86



THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.