

REPORT of SURVEY for REPAIRS, &c.

No. 3743

Received in London Office

MONDAY 21 1887

No. in Survey held at

Beaulby
St. "Jessie"

Date, First Survey 14th Jan Last Survey 15 Jan 1887

Reg. Book. 220 on the

Master W. Millar 78

YEAR. MONTH.

TONNAGE:—

NET 99

GROSS 108

UNDER DECK 108

Built at Kingston

By whom Spence

When 1878 - 6

Owners G. Thomson

Port belonging to Banff

Owners' Address Port Gordon

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Name of Dock On the ground at Beaulby

Destined Voyage Not fixed

Length of Poop ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft. ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. 3739

Port Abn.

Classed 10

A1

H184

4-84

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE

Damage. See Aberdeen Report No. 3739.

This vessel was placed on the ground. & then careened to the port & starboard side.

On Examination the bottom was found in good order & free from any damage.

The bottom recaulked, the deck also caulked where necessary, the same tested & found satisfactory, the outside & inside examined & found in good order.

PRESENT CONDITION OF THE

Decks	good	Plank (Bottom) & Counter	Good	Ceiling	Good	Boats	Good
Waterways	✓	Treenails or Stakes	✓	Rudder	✓	Masts, Yards, &c.	✓
Comings	✓	Breasthooks & Stemson	✓	Windlass & Capstan	✓	Condition, how ascertained	from deck
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Pumps	✓	Sails	Good
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the openings	where seen	Cement (if Iron Ship)	✓	Anchors	No. of 2 B-15. 1K
Planksheers	✓	Ditto ditto at other places	seen	Caulking of Bot'm, D'k, & Watrways	Good	Cables	Good where seen
Sheerstrakes	✓	Keelsons	Good	Copper, or Y.M.	✓	Hawsers & Warps	Good
Topsides	✓	Clamps & Shelves	✓	(State if on Felt.)	✓	Standing & Running Rigging	✓
Wales	✓			When put on	✓	Hatches	Good.
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	Good	Scuppers	Good	Cargo & Main Hatchways	Good

General Observations, Opinion as to Class, &c.:

This vessel is now in good order & eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27.

Office Fee (if chargeable) per Scale II., Sec. 27.

Survey Fee (per Section 28)

Special Damage Fee (if any) (per Sec. 28)

*Certificate (if required) to be sent as per margin

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

£ : :

£ : :

£ 1 : 1 : 0

£ : :

£ : :

£ 2 : 13 : 6

£ : :

not

received

31.1.1887

1/2/87

John H Heck.

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 1 FEB 1887

Character assigned

10