

# REPORT of SURVEY for REPAIRS, &c.

Received in London Office. **WEDNES. 28 SEPT 1887**

No. 3807

Port of *Aberdeen*

No. in  
Reg. Book.

Survey held at

*Aberdeen*

Date, First Survey

(No. of Visits)

Last Survey *19 Sept 1887*

1887

313 on the

*S. S. "Benamain"*

Master *W Jester* 86-86.

YEAR.

MONTH.

TONNAGE:—

NET *247*

GROSS *381*

UNDER DK. *308*

Built at *Aberdeen*

By whom *Hull Russell & Co*

When *1878*

*5*

Owners *J & A Davidson*

Port belonging to *Aberdeen*

Owners' Address *Aberdeen*

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

*Afloat*

Name of Dock

*Victoria*

Destined Voyage

*Coasting*

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned,  
if a Wood Ship.

Character in  
Register Book.

Classed

*100. A.1*

Last Survey, No. *3786*

Port

*Aber*

*S.S. No 2-83*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard

in Summer

in Winter

as painted on Ship

ins.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *To complete S.S. No 2.*

*The inside of the coal bunker now examined & found satisfactory.  
For remainder of Survey See above Report No 3786.*

## PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Wat'rways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
	<i>Good</i>		
			Hatches

General Observations, Opinion as to Class, Recommendation, &c.:

*this vessel as far as seen is in good order & eligible  
in my opinion to remain as classed.*

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28) .....	£	:	:
Special on Damage Fee (if any) (per Sec. 28) .....	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable) .....	£	:	:
Second Surveyor's Fee (if any) .....	£	:	:

Fees  
received by me,  
*188*

*John H Heck.*  
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

**FRIDAY 30 SEPT 1887**

Character assigned