

REPORT of SURVEY for REPAIRS, &c.

3989

MON - 1 JUL 89
88 7 11 1 NOW

No. 3989 Date of Writing Report June 29 1889 Port of Aberdeen
 No. in Survey held at Aberdeen Date, First Survey June 19th Last Survey June 28th 1889
 Reg. Book. 200 on the "Dewdrop" (No. of Visits) Master R Bond

TONNAGE:— NET 14 GROSS 55 UNDER DK. 55
 Built at Anstruther By whom W. Jarvis When 1883 5
 Owners W. H. Burn Port belonging to Dundee
 Owner's Address (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Slipway Name of Dock A Hall & Co's Slipway Destined Voyage Trawling
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 3972 Port Aberdeen. Classed Fishing purposes only A- 5-89
 Society's Freeboard (if assigned) in Summer ft. ins. H.S. Abn. 58.
 as painted on Ship in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs

The vessel placed on the above slipway for the purpose of ascertaining the amount of damage stated to have been sustained through being ashore at Slaines on the 17th inst

On examination the keel from amidships forward was found damaged and broken at the scarp also the garboard strake and the adjoining strake badly chipped on the port side amidships.

A new length of keel (American Elm) 4ft 3" has been fitted and fastened with 7/8" galvanised bolts. A new scarp made in the after length of keel and fastened with 3/4" Yellow metal bolts and the garboard strake and the adjoining strake renewed where damaged

PRESENT CONDITION OF THE	Good	Plank (Bottom) & Counter	Good	Ceiling	Wood	Boats	Good
Decks	Good	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Waterways	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	from deck
Comings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	"
Up'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"	Cement (if Iron Ship)	"	Anchors	No. of 213
Low'r Dk. Beams & Fastenings	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	"
Planksheers	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Sheerstrakes	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Topsides	"					Hatches	"
Wales	"						
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.		Scuppers		Cargo & Main Hatchways	

General Observations, Opinion as to Class, Recommendation, &c.:

The above vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to be noted. 6-89. and d'ys 6-89 in the Register Book

Entry Fee (if chargeable) per Scale I., Sec. 27...	£			Fees applied for, June 28 1889 Received 2/14/89 1889 G. D. Hindmarsh Surveyor to Lloyd's Register of British & Foreign Shipping.
Office Fee (if chargeable) per Scale II., Sec. 27...	£			
Survey Fee (per Section 28)	£			
Special on Damage, Fee (if any) (per Sec. 28)	£	2	2	
*Certificate (if required) to be sent as per margin	£			
Travelling Expenses (if chargeable)	£			
Second Surveyor's Fee (if any)	£			

Committee's Minute TUE - 2 JUL 89
 Character assigned A- Fishing purposes only
 BS 6/89

State if a machinery, or if not whether, and when, she will be sent

Insert Character precisely as in Register Book.

