

No. \_\_\_\_\_

(Received in London Office, \_\_\_\_\_)

**TESTS OF BOILER STEEL.**

Tests of <sup>1</sup> Steel plate manufactured by John Brown & Co. Ltd. of Sheffield  
 for Boiler No. \_\_\_\_\_ to be constructed by Victor Coats of Belfast  
 for 25269.

Date first visit 8<sup>th</sup> Nov last visit 8<sup>th</sup> Nov No. of Visits one

The plate specified in the accompanying copy of Advice Notes were rolled from  
one charges. The tensile test has been applied to one samples as set forth below,  
 and the temper and bending tests one

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Boiler	374	6	4177	.81	1.06	.854	24.5	28.5	276	16" 0" x 7" 3/4" x 13/16"

Fee ..... £ : ✓ : ✓

Expenses £ 1 : 0 : 0

£ 1 : 0 : 0 To be paid by \_\_\_\_\_

© 2021  
  
 David James  
 Surveyor, Lloyd's Register,  
 London