

"City of Dublin" Belfast Report No. 3399.

LOYD'S REGISTER OF BRITISH AND FOREIGN SHIPBUILDERS

No. 5199

(Received at London Office,



TESTS OF BOILER STEEL.

Tests of 4 Steel plates manufactured by Messrs Beardmore & Co of Parkhead for Boiler No. 124 to be constructed by Messrs J & J Thomson of Glasgow for

Date first visit July 4th last visit July 6th No. of visits Two

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to Two samples as set forth below, and the temper and bending tests to a sample from each plate.

The 4 plates were cut from 3 slabs.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Br.th.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	6-0" x 18 3/8" x 1"	M 143		909	1.01	1.13	1.141	33.5	29.3	25	
	16-3 x 30 1/2 x 1/2	M 145		42	.5	1.26	.63	18.2	28.8	28	

W.P. 26/7/87

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

© 2019
 Lloyd's Register Foundation
 Walker & Robson
 Surveyor, Lloyd's Register
 Glasgow 23/7/87