

No. ....

**TESTS OF BOILER STEEL.**

Tests of mild Steel plates manufactured by *Messrs John Brown & Co of Sheffield*  
 for Boiler No. *198* to be constructed by *Messrs Harland & Wolff*  
 for *S.S. "Lycia" Bel. Report No 31423*

Date first visit *28 Jan'y 87* last visit *24 Jan'y* No. of visits *2*

The *8* plates specified in the accompanying copy of Advice Notes were rolled from  
*4* charges. The tensile test has been applied to *one* sample as set forth below,  
 and the temper and bending tests to *8* samples & found *satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
<i>14</i>	<i>Furnace</i>	<i>771A</i>	<i>2</i>	<i>14</i>	<i>.58</i>	<i>1.68</i>	<i>.939</i>	<i>25</i>	<i>26.6</i>	<i>31</i>	<i>M</i> <i>17.2.97</i>

Fee ..... £ : :  
 Expenses £ : :  
 £ : : \_\_\_\_\_

To be paid by .....

*W. Brown*  
 Surveyor, Lloyd's Register,  
 London  
 © 2019  
 Foundation  
 BELSH-0288