



# THE STEEL COMPANY OF SCOTLAND, LIMITED.

Test Room Sheet *Newton* Works, the *third* day of *September* 18*89*

ORDER NO.	QUALITY.	CHARGE NO.	SAMPLE NO.	-SIZE OF SAMPLE.			BREAKING STRAIN.		EXTENSION			CONDITION.		INITIAL STRAIN.		SIZE OF FRACTURE.				REMARKS.
				Bth.	Thk.	Area.	Actual Tons.	Per sq" Tons.	% Ins.	% Ins.	% Ins.	Long or Cross.	Annealed or Unannealed.	Actual Tons.	Per sq" Tons.	Bth.	Thk.	Area.	%	
<p>Harland and Wolff's quadrant for tiller N° 218 Ship. Was not dropped, owing to peculiar construction</p> <p>Subjected to hammering test on August 28<sup>th</sup> with satisfactory results.</p> <p>H.T. 1.20 .49 .588 19.9 33.8 26.0 H.T. 1.20 .50 .600 20.2 33.6 24.0</p> <p>Bent to 89° without breaking.</p>																				<p>J. H. Gray Surveyor to Lloyd's Register Glasgow</p>





© 2019  
Lloyd's Register  
Foundation.

8656-0077

© 2019



Lloyd's Register  
Foundation

BEL56-0077