


# THE STEEL COMPANY OF SCOTLAND, LIMITED.

Test Room Sheet

Works, the 23<sup>rd</sup> day of March

1889

CHARGE No.	SAMPLE No.	SIZE OF SAMPLE.			SIZE OF FRACTURE.				INITIAL STRAIN.		BREAKING STRAIN.		LENGTH.		EXTENSION.		CONDITION.		QUALITY.	ORDER No.
		Bth.	Thk.	Area.	Bth.	Thk.	Area.	%	Actual Tons.	Per sq " Tons.	Actual Tons.	Per sq " Tons.	Before Breaking.	After Breaking.	% Ins.	% Ins.	Annealed or Unannealed.	Long or Cross.		
	H.W	1.24	.48	.595							18.5	31.0			2.5					
Messrs Harland & Wolff's Stern Frame for 223 Ship																				
 <p>Bent 1' square</p> <p>Bent through an angle of 92° without any sign of fracture.</p> <p>B. Ryder 23<sup>rd</sup> March 1889</p>																				

36656-0244

BeL56-0244

should be struck out as

Lloyd's

No. 2111.



48 Wolffe 223  
Stern Frame Castings  
March 25<sup>th</sup> 89

"Alexander Elder"  
Belfast Report  
No 3685



© 2019

Lloyd's Register  
Foundation