


Michigan Bel. 3718
THE STEEL COMPANY OF SCOTLAND, LIMITED.

Test Room Sheet *Newton* Works, the *4th* day of *September* 188*9*

CHARGE No.	SAMPLE No.	SIZE OF SAMPLE.			SIZE OF FRACTURE.			INITIAL STRAIN.		BREAKING STRAIN.		LENGTH.		EXTENSION.		CONDITION.		QUALITY.	ORDER No.	REMARKS.
		Bth.	Thk.	Area.	Bth.	Thk.	Area.	%	Actual Tons.	Per □ " Tons.	Actual Tons.	Per □ " Tons.	Before Breaking.	After Breaking.	% Ins.	% Ins.	Annealed or Unannealed Cross.			
	<i>H. T.</i>	<i>1.23</i>	<i>.48</i>	<i>.590</i>							<i>18.0</i>	<i>30.5</i>			<i>26.5</i>					
	<i>H. T.</i>	<i>1.23</i>	<i>.50</i>	<i>.615</i>							<i>18.8</i>	<i>30.5</i>			<i>22.5</i>					
<i>Harland and Wolff's Stern Frame for No 227 Ship</i>																				
 <p style="text-align: center;"><i>Bent to 90° without fracture.</i></p>																				
<p style="text-align: right;"><i>Mr. H. May.</i> <i>Surveyor to Lloyd's Register</i> <i>Glasgow</i></p>																				



© 2019

Lloyd's Register
Foundation

BEL 57-0056