



THE STEEL COMPANY OF SCOTLAND, LIMITED.

Test Room Sheet *Newton* Works, the *11th* day of *June* 18*94*

ORDER No.	QUALITY.	CHARGE No.	SAMPLE No.	SIZE OF SAMPLE.			BREAKING STRAIN.		EXTENSION.			CONDITION.		INITIAL STRAIN.		SIZE OF FRACTURE.				REMARKS.
				Bth.	Thk.	Area.	Actual Tons.	Per 3/4 Tons.	% 8 Ins.	% 1 Ins.	% 1 Ins.	Long or Cross.	Annealed or Unannealed.	Actual Tons.	Per 3/4 Tons.	Bth.	Thk.	Area.	%	
<i>Rudder frame for Messrs Workman Clark & Co's No 112</i>																				
<i>90" dia. 6.36 19.5 30.6 15.5 Bent to 92% without fracture 8/6/94</i>																				
																				
<i>Dropped & hammered with good results 2/5/94</i>																				
<i>Charles Cooper</i>																				



© 2019
Lloyd's Register
Foundation

BEL64-0083



© 2019

Lloyd's Register
Foundation

BEL64-0083

112

Casting

Rudder frame

"Copack"

Bel. First Entry Rpt. No 4430



© 2019

Lloyd's Register
Foundation