

THE STEEL COMPANY OF SCOTLAND, LIMITED.

Test Room Sheet *Newton* Works, the *5th* day of *February* 18*95*

ORDER NO.	QUALITY.	CHARGE NO.	SAMPLE NO.	SIZE OF SAMPLE.			BREAKING STRAIN.		EXTENSION.			CONDITION.		INITIAL STRAIN.		SIZE OF FRACTURE.				REMARKS
				Bth.	Thk.	Area.	Actual Tons.	Per 3" Tons.	% Ins.	% Ins.	% Ins.	Long or Cross.	Annealed or Unannealed.	Actual Tons.	Per 3" Tons.	Bth.	Thk.	Area.	%	
<p><i>Rudder frame for Messrs Workman Clark & Co's N° 94</i></p> <p><i>.87 dia .594 17.7 29.8 21.0 Bent to 101° without fracture 25/1/95</i></p> <p><i>Dropped and hammered with good results 22/1/95</i></p> <p><i>Charles Cooper</i></p>																				



© 2019

Lloyd's Register
Foundation

BEL64-0204

94

Casting (Steel)

Rudder frame

"Star of New Zealand"

Belfast First Entry Rpt.

No. 44 '75



© 2019

Lloyd's Register
Foundation