

4th. When the ship was complete, and before the
plating was finally coated or cemented.. }

5th. After the ship was launched and equipped

3/11 7/11 6/11 8/11 15/11 24/11 27/11 7/12 16/12 23/12 3/1. 1885

this cas

ality of

4"

and

arg;

BGN1105/223

REPORT, No.

1014 FROM

Berger

DATE

26 Jan 1885

ON THE

S. S. Ganger Koly

REMARKS OF THE CHIEF SURVEYOR.

It is submitted that this vessel appears worthy of
the favorable consideration of the Committee to be classed


100A-1. Spar Decked as recommended.

One deck iron, Spar 3x

3 br Beams.

Equipment letter (70")

S.B. particulars appended



© 2021

Lloyd's Register
Foundation

essel, or if spar, or awning decked; and the lengths of poop, bridge, fore-castle, or raised quarter deck. (If double bottom, state particulars on separate form) Pitch of
ved from oxidation? Inside three coats of paint. and bottom with cement Outside three coats of paint