1st Foothooks	14	14	12				
2nd Ditto	12	12			Bilge Planks	4½	Bilge
3rd Ditto	11	10			Bilge to Wales	4½	Ceiling
							Ditto

No 2. The Terrace, Croft near Darlington
July 30th 1863—

Mr Geny B Seyfang
Dear Sir

I have received Mess Jaines Scott & Co letter about the "Swanstand" being nearly completed, and Main Deck secured & as recommended by us, and having sent me the Certificates of Attestation of the Recess Timbers (not mine for the Stream or Keeps) I have added the same on the Report, also have copied the Naval Store Keepers Certificate upon Mess Jaines Scott & Co letter (which I enclose) of the Chains coming from the Dock Yard, and so far as our Judgment goes, they appear to be very good—

Before I left saw the Plastic Cotton put for examination of Timbers, saw in and bolt Shafted with 8 Inch Ash Oak Red Pine, treenailed through each timber & through bolted with Iron, the Ironwork of the Port were closed by shutting some of the planking between, and those intended to be kept for the purpose of loading & unloading in lieu of each Gateway were to be secured as other two Pairs, well lipped at each side upon the timbers and all thoroughly caulked, so that the Main deck would be a perfect deck, with Scuppers, Tunings, (which are very good) & proper Hatches Companionway &c &c and now send you the Report filled & complete and will thank you to send the Certificate to Mess Jaines Scott & Co at Swanstown—

I have been Shopping for the last few days from my Old Aunt, but feel a little better to day & hope will be able to proceed Home next week, better I trust for my Holiday. As a letter from there to day I am glad I have not been troubled up to that time— excuse any errors in this and remain Dear Sir Yours Most Respectfully

George Wright

CBK93-0127

© 2019 Lloyd's Register Foundation

Planking Inside.—The Limber-strakes and Bilge-strakes are African Oak

The Ceiling, Lower Hold, and between Decks African Oak Shelf Pieces and Clamps