

ENNAGE under
Fonnage Deck . .)

540

ONE OR TWO DECKED VESSEL.

CLASS 100 A

Year of Appointment

(1) As master
owner of vessel
(2) As master
vessel

Received by Chief Surveyor J. G. 99

Received from Chief Surveyor

VESSEL'S NAME St. Pku. "Sachsen"

Report Ins. No. 2562

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Course of Survey First entry

It is submitted that before this case receives the consideration of the Committee, the following wire should be sent to the Queenstown Surveyor :- "Sachsen forward test certificates steel and rigging plan by today's mail without fail".

C.H.P.
5/6/99



© 2019

Lloyd's Register
Foundation

CRK93-0353

S, Bridge Deck, Angle, Bulb Angle, } ✓
Plate, or Tee Bulb.
Angles on ditto, No.
Poop Deck Stringer Plate, breadth & thickness

ved
ov
3-1
tw
with
of Be
Beam
20ths
in Ship
9
9
6
6
7
6
6
7
7
9
7
8
8