

Port of Dublin

March 31st 1900

REPORT ON MASTS, SPARS, AND RIGGING.

Sir

Having, in accordance with your instructions, examined
Masts, Spars, and Rigging, and Iron Work of same, of the
Iron Schooner "British Queen"
to report that I found The condition of the Fore
mast-wood good. Main mast-wood good.
Mizzen mast-wood good. Jib boom wood good.
Booms & Gaffs wood good. Wedges taken
& replaced. masts & spars bored. New coats
of paint. Standing rigging in good condition.
Chain plate on main mast renewed & one on
mizzen mast new pin fitted. Shackle pin on
mizzen renewed for Bobstay old hole in stem
drilled up & new hole drilled remainder of
work in good condition

A. Aibken

Boorman Shipwright

Surveyor,

Lloyd's Register of British & Foreign Shipping,

Dublin



DOB99-0075