

Barque "OLWEN".

It is submitted the Dublin Surveyor be requested  
to ascertain and report to this Office when the alteration  
to the rudder to which he refers in his letter was made.

Sr. 30/6/14

C.T.

30.6.14.

*for*



© 2019

Lloyd's Register  
Foundation

DLB94-0160