

ANNUAL SURVEYS.

No. 4412 Survey held at Dundee Date, first Survey 8th June Last Survey 13th June 1881
 No. in on the S. "Baron Clonoway" Master Foster
 Reg. Book. 108 Tonnage 1632 Built at Greenock When built 1875 - 8 mo.
 By whom built J. S. Scott Owners J. Mc Cann & Co
 Port belonging to Greenock Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 5242 Port of hpt
 Present Condition of the
 Decks grd Riveting grd
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " ~~Timbers of the Frame at the Openings~~ "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
~~Plank~~ (Bottom) and Counter " ~~Copper or V.M.~~ Cement When put on 75
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers grd Cargo and Main Hatchways grd Hatches grd
 General Observations, Opinion as to Class, &c.

Classed 100 A1
 Years assigned. 7. 80
 Character in Register Book. S.S. Lon No 1-79
 Windlass and Capstan Complete grd
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from deck
 Sails Complete
 Anchors, No. of 3 B 15 2 K
 Cables Complete
 Hawser and Warps grd
 Standing and Running Rigging "

*This vessel has now been placed in proving dock. The bottom cleaned and
 receded. is in good condition & eligible in my opinion to remain as classed*

Committee's Minute Tuesday, July, 12th 1881.
 Character assigned 100 A1

Geo. T. Cooper
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18

No. 23 Survey held at Dundee Date, first Survey 8th June Last Survey 13th June 1881
 No. in on the S. "MacLard" Master W. Jutye
 Reg. Book. 23 Tonnage 1556 Built at Dumbarton When built 1879 - 5 mo.
 By whom built A. McMillan & Co Owners A. McMillan & Co
 Port belonging to Glasgow Destined Voyage Shields
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 27146 Port of Iron
 Present Condition of the
 Decks grd Riveting grd
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " ~~Timbers of the Frame at the Openings~~ "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
~~Plank~~ (Bottom) and Counter " ~~Copper or V.M.~~ Cement When put on 79
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers grd Cargo and Main Hatchways grd Hatches grd
 General Observations, Opinion as to Class, &c.

Classed 100 A1
 Years assigned. 6. 80
 Character in Register Book. S.S. Lon No 1-79
 Windlass and Capstan Complete grd
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from deck
 Sails Complete
 Anchors, No. of 3 B 15 2 K
 Cables Complete
 Hawser and Warps grd
 Standing and Running Rigging "

*This vessel has now been placed in proving dock. The bottom cleaned and
 receded. is in good condition & eligible in my opinion to remain as classed*

Committee's Minute Tuesday, July, 12th 1881.
 Character assigned 100 A1

Geo. T. Cooper
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18