


2nd. On the plating during the process of construction } 15. 16. 17. 20. 23. 26. 30. June 2. 5. 9. 12. 20. 25. July 1. 2. 4.  
3rd. When the beams were in and fastened, and before the decks were laid.... }

REPORT, No. 4740 FROM *Dundee*  
ON THE *Dresden*  
REMARKS OF THE CHIEF SURVEYOR.

DATE *5/8/84*

*This vessel has been built in accordance with the approved plans appended, and appears to be worthy to be classed 100 A1 Steel as recommended 15% (part Steel).*

*Double Bottom particulars appended.*



© 2021

Lloyd's Register  
Foundation

DUN210-0092

*The material, stamped LR & invoiced as having been tested by the manufacturer, is in the body of the hull.*