

in way of Engines and Boilers

floors, Through Plate, or Intercoastal Plate

Sent to Chief Surveyor 24/8/95

Received from Chief Surveyor

VESSEL'S NAME Steel S.S. Sardinia

Report Jun No. 6115

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Classification

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A.1. Steel as recommended.

+ 100 A.1. Steel

2 Stks (U. Std)

WB = Cell DB a 52' UE & B 40' f 94' 228 T. F.P.T. 272 A.P.T. 182

F.K. Cem.



E. J. M.
24/8/95

Lloyd's Register
Foundation

DUN 123-0317

Vessel	Rule	Horizontal	Vertical
		Inches	Inches