

1.

Sent to Chief Surveyors 18. 10. 00

Received from Chief Surveyors

VESSEL'S NAME *Sm S. S. "Pannure"* Report *Fal.* No. *4355*  
*ex Sm S. S. "Pannure"*For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *First entry* *When due*

It is submitted the Falmouth Surveyor be informed that the 2nd. S.S. No. 3, repairs and alterations carried out in this steamer should be reported by him on a repair report form No. 8 in the usual manner, and he should state on the report his recommendation as to the classification of the vessel.

*C. H. J.*  
*18/10/00**Dr. to Fal. 19/10/00*

© 2019

Lloyd's Register  
Foundation

FAL138-0030