

# REPORT of SURVEY for REPAIRS.

786

No. 786 Survey held at Glasgow Date 23<sup>d</sup> September 1853  
 on the Barge "Lancaster" Master William C. Cydeman  
 Tonnage 283 Built at Gundahard When built 1844  
 By whom built 333 Owners Deeddale  
 Port belonging to Parmouth Destined Voyage Genoa  
 If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 11325 Port Liverpool Classed S.A. 1

## REPAIRS

*Of Damage at Malta in March last; Shipped the Yellow Metal Sheathing; Renewed the entire keel and several Planks on the Starboard Side and Bottom and Buttock with Adriatic Oak and a number of Greening and Bolts in the Bottom and Caulked over all. At Present Caulked the Bottom and Sheathed with Yellow Metal over Paper*

## Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Winch Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>2 do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>3 do</u>
Upper Deck Beams & Fastenings	<u>Sound</u>	Timbers of the Frame	<u>Where seen do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>Sound</u>	Keelsons	<u>do</u>	Sails	<u>do</u>
Planksheers	<u>good</u>	Clamps and Shelves	<u>do</u>	Anchors	No. of <u>3 B&amp; 1 Stem 1 Jedge</u>
Sheerstrakes	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>Complete and Good</u>
Topsides	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>do do</u>
Wales	<u>do</u>	Copper	<u>Yellow Metal</u> When put on <u>Aug 1853</u>	Standing & Running Rigging	<u>do do</u>
Plank (Bottom) and Counter	<u>do</u>				

General Observations and Opinion, *Ship in good Condition and fit for the safe Conveyance of dry and Perishable Cargoes to and from all parts of the World and may Continue as Classed*

The Amount of Fee.....£ 1 : " : " is received by me,

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute 30<sup>th</sup> Sept 1853

Character assigned CRP 3 D 1



© 2019  
Lloyd's Register  
Foundation

GLS/41-0237