

REPORT of SURVEY for REPAIRS.

819

No. 819 Survey held at Glasgow Date 26th November 1853
 on the Barge Anna Robertson Master John H. Mossey
 Tonnage 309 Built at Sunderland When built 1842
 By whom built 317 Owners Mossey & Co.
 Port belonging to Southborough Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 146 Port Glasgow Classed 9A.1
 REPAIRS At Present Stripped the Yellow Metal Sheathing and Cleaned the Bottom

Renewed all the Treennails from the lower part of the Bilge to the Gunwale and several Decayed Bolts; Caulked from Keel to Gunwale, Waterways and Round the Comings and Resheathed the Bottom with Yellow Metal over Felt

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>New & Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>2 do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>2 do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame	<u>Where Seen do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Keelsons	<u>do</u>	Sails	<u>do</u>
Planksheers	<u>do</u>	Clamps and Shelves	<u>do</u>	Anchors	No. of <u>3 1/2 1 Stem Wedge</u>
Sheerstrakes	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>Complete & Good</u>
Topsides	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>do do</u>
Wales	<u>do</u>	Copper	<u>Yellow Metal</u> When put on <u>Nov 1853</u>	Standing & Running Rigging	<u>do do</u>
Plank (Bottom) and Counter	<u>do</u>				

General Observations and Opinion.

Ship in good Condition and fit for the safe Conveyance of Dry and Perishable Cargoes to and from all parts of the World and may Continue as before

The Amount of Fee.....£ 2 : : is received by me,

Special..... : : :


Certificate (if required) : : :

Committee's Minute

Character assigned

29 Nov 1853

Class 3 A, 1



© 2019

Lloyd's Register Foundation

GLS141-0261