

REPORT of SURVEY for REPAIRS.

No. 1080 Survey held at Glasgow Date 10th May 1855
on the Brig "Martha" Master Robert Woodie
Tonnage 185 Built at Cape Breton When built 1841
By whom built ✓ Owners John Mitchell
Port belonging to Glasgow Destined Voyage Opports
If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 742 Port Glasgow Classed 3. A. S. 3. C.
S. S. 53. 3. C.

REPAIRS New Waterways from the Bow to 10 feet from the Stern
on each side with Yellow Pine
Five End of Deck doubled to the Off Side of the Windlass with
Yellow Pine over Felt
Caulked over all

Present Condition of the

Decks <u>in fair Condition</u>	Treenails <u>Not Seen</u>	Windlass and <u>Capstan</u> <u>Good</u>
Waterways <u>Part new & Good</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2 Good</u> <u>do</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>2</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Where Seen good</u>	Sails <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do do</u>	Anchors No. of <u>2 13. 1 14. 1 15. 1 16. 1 17. 1 18. 1 19. 1 20. 1</u>
Sheerstrakes <u>do</u>	Ceiling <u>do do</u>	Cables <u>Good</u>
Topsides <u>do</u>	Rudder <u>do do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>1853</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion Appears in good Condition fit for the safe conveyance
of dry & perishable Cargo and may continue as before

The Amount of Fee.....£ : 10 : - is received by me,

May 11

Special..... : : :

Certificate (if required) : : :

Committee's Minute 22nd May 1855

Character assigned F. 1

Record repairs

Wm Robertson

