

ANNUAL SURVEYS.

1089

No. 1089 Survey held at Glasgow Date 30th May 1855
 on the Brig Pyra Master Gilbert Ross
 Tonnage 213 Built at Greenock When built 1839
 By whom built 218 Owners Kirby & Co
 Port belonging to Whitby Destined Voyage From France
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 578 Port of Glasgow Classed 9. A. 1. S.S. 52
C 3 52

The present Condition of the

Decks <u>On Bad Condition</u>	Treenails <u>Not Seen</u>	Windlass and Capstan <u>Winch Good</u>
Waterways <u>Not Seen</u>	Breasthooks and Stemson <u>✓</u>	Pumps <u>do</u>
Comings <u>✓</u>	Transoms, Pointers, and Crutches <u>✓</u>	Boats <u>Two</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>✓</u>	Masts, Yards, &c. <u>Complete</u>
Lower Deck Beams & Fastenings <u>✓</u>	Keelsons <u>✓</u>	Sails <u>do</u>
Planksheers <u>✓</u>	Clamps and Shelves <u>✓</u>	Anchors No. of <u>2 1/2 10 lb. shot</u>
Sheerstrakes <u>✓</u>	Ceiling <u>✓</u>	Cables <u>Complete</u>
Topsides <u>✓</u>	Rudder <u>✓</u>	Hawsers and Warps <u>do</u>
Wales <u>Not Seen</u>	Copper <u>Partial</u> When put on <u>1852</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, The Decks particularly Amidships between the
Waterways and Hatchways on each side are in bad Condition, Planks
badly shifted several having two Planks on the same Beam and
no stake between, 4 or 5 Stakes on each side & other parts of the
Deck will require to be renewed. In my opinion her Character should be
expunged till repaired and strictly surveyed

Committee's Minute 18th June 1855

Character assigned Expunge Character

Notice to crew
12 June 1855
For Change of Character
Wm. Robertson
 Certificate (if required) ✓

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion, _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register

Certificate (if required)