

ANNUAL SURVEYS.

Rec. 25/10/58 1493

No. ¹⁵⁷ 1493 Survey held at Glasgow Date 13th October 1858
 on the Barge Lauriston Master Alexander Davidson
 Tonnage 400 Built at Sunderland When built 1857
 By whom built _____ Owners Anderson
 Port belonging to Aberdeen Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 4130 Port of Sunderland Classed 9 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2 Metal</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>3</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Complete & Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u> <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1/2</u> <u>1 Iron Wedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>2 Metal</u> When put on <u>Oct 58</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways New & Good
At Present, Shipped the Yellow Metal Sheathing, Cleaned the Bottom, Caulked from Keel to Gunwale, Sheathed the Bottom with Yellow Metal over Selt; As now in good & efficient Condition fit for the safe Conveyance of dry & perishable Cargoes to and from all parts of the
 Committee's Minute 26th October 1858 Valid and to continue as Ordered
 Character assigned 9 A 1 record YMLD Wm Robertson
 Certificate (if required)

No. ³⁹⁰ 1493 Survey held at Glasgow Date 18th October 1858
 on the Ship Alliance Master Charly J. Card
 Tonnage 552 Built at New Britain When built 1855
 By whom built _____ Owners Barf & Co
 Port belonging to Halifax Destined Voyage New Orleans
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 14110 Port of Lpool Classed 4 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2 Metal</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>3</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Complete & Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u> <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1/2</u> <u>1 Iron Wedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>2 Metal</u> When put on <u>Oct 58</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways Good
Shipped the Yellow Metal Sheathing, Cleaned the Bottom, Caulked over all; Sheathed the Bottom with Yellow Metal over Selt; As in good & efficient Condition fit for the safe Conveyance of dry & perishable Cargoes to & from all parts of the World and to continue as Ordered
 Committee's Minute 26th October 1858
 Character assigned 4 A 1 record YMLD Wm Robertson
 Certificate (if required)