

# ANNUAL SURVEYS.

1510

Rec 7/12/18

No. 1510 Survey held at Glasgow Date 4<sup>th</sup> December 1858  
 on the Ship Jasper Master Matthew Irvine  
 Tonnage 623 Built at Dublin When built 1854  
 By whom built 578 Owners Math & Co  
 Port belonging to Glasgow Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 20617 Port of London Classed 6.1.1.  
 56

The present Condition of the

|   |  |  |
|---|--|--|
| Decks <u>Good</u>                         | Treenails <u>Good</u>                      | Windlass and Capstan <u>Good</u>                 |
| Waterways <u>do</u>                       | Breasthooks and Stemson <u>do</u>          | Pumps <u>2 Metal</u> <u>do</u>                   |
| Comings <u>do</u>                         | Transoms, Pointers, and Crutches <u>do</u> | Boats <u>3</u> <u>do</u>                         |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame <u>do</u>             | Masts, Yards, &c. <u>Complete &amp; Good</u>     |
| Lower Deck Beams & Fastenings <u>Good</u> | Keelsons <u>do</u>                         | Sails <u>do</u> <u>do</u>                        |
| Planksheers <u>Good</u>                   | Clamps and Shelves <u>do</u>               | Anchors No. of <u>31 3/4</u> <u>1 Iron Wedge</u> |
| Sheerstrakes <u>do</u>                    | Ceiling <u>do</u>                          | Cables <u>Complete &amp; Good</u>                |
| Topsides <u>do</u>                        | Rudder <u>do</u>                           | Hawsers and Warps <u>do</u> <u>do</u>            |
| Wales <u>do</u>                           | Copper <u>do</u> When put on <u>Dec 57</u> | Standing & Running Rigging <u>do</u> <u>do</u>   |
| Plank (Bottom) and Counter <u>do</u>      |  |  |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

At present 1857 At Bombay, Shipped the Yellow Metal Sheathing, Caulked over all and sheathed the Bottom with Copper over Salt.  
 At present Shipped the Carboard & Steel Copper to examine for a Leak.  
 Caulked the Carboard, Leaky & Butts & Sheathed. do now tight & in a good

Committee's Minute 10<sup>th</sup> December 1858 efficient Condition and to continue as  
 Character assigned Good Clasped Robertson

record copper

Certificate (if required)

Special Survey See 2.1.1

No. 1510 Survey held at Glasgow Date 6<sup>th</sup> December 1858  
 on the Barge Duke of Wellington Master John Smith  
 Tonnage 487 Built at Dumbarton When built 1842  
 By whom built 560 Owners Angell & Co  
 Port belonging to Glasgow Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 1202 Port of Glasgow Classed 10.1.1.  
 56, 1 Year

The present Condition of the

|   |  |  |
|---|--|--|
| Decks <u>Good</u>                       | Treenails <u>Good</u>                      | Windlass and Capstan <u>Good</u>                 |
| Waterways <u>do</u>                     | Breasthooks and Stemson <u>do</u>          | Pumps <u>4 in</u> <u>do</u>                      |
| Comings <u>do</u>                       | Transoms, Pointers, and Crutches <u>do</u> | Boats <u>3</u> <u>do</u>                         |
| Upper Deck Beams & Fastenings <u>do</u> | Timbers of the Frame <u>do</u>             | Masts, Yards, &c. <u>Complete &amp; Good</u>     |
| Lower Deck Beams & Fastenings <u>do</u> | Keelsons <u>do</u>                         | Sails <u>do</u> <u>do</u>                        |
| Planksheers <u>do</u>                   | Clamps and Shelves <u>do</u>               | Anchors No. of <u>31 3/4</u> <u>1 Iron Wedge</u> |
| Sheerstrakes <u>do</u>                  | Ceiling <u>do</u>                          | Cables <u>Complete &amp; Good</u>                |
| Topsides <u>do</u>                      | Rudder <u>do</u>                           | Hawsers and Warps <u>do</u> <u>do</u>            |
| Wales <u>do</u>                         | Copper <u>do</u> When put on <u>Dec 58</u> | Standing & Running Rigging <u>do</u> <u>do</u>   |
| Plank (Bottom) and Counter <u>do</u>    |  |  |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

At present Shipped the Yellow Metal Sheathing, Cleaned, Caulked and sheathed the Bottom with Yellow Metal over Paper, Upper Course Salt. do now in good & efficient Condition & to continue as

Committee's Minute 10<sup>th</sup> December 1858

Character assigned Rest 7

record

Certificate (if required).

Lloyd's Register Foundation

GLS142-0254