

# ANNUAL SURVEYS.

1520

No. 1528 Survey held at Bowling Date 27th January 1859  
 on the Big Woodside Master John Edwards  
 Tonnage 114 Built at Glasgow When built 1839  
 By whom built Scott Owners Mrs. Jean & Saml.  
 Port belonging to Glasgow Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Patent Ship  
bt 1B N. R. 1000 S. 2000 S. 2

Last Survey, No. 1216 Port of Glasgow Classed C 3 \*A. 1 SS. 374

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>2</u> <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>White Pine</u> <u>do</u>	Masts, Yards, &c. <u>Complete &amp; Good</u>
Lower Deck Beams & Fastenings <u>Sound</u>	Keelsons <u>do</u> <u>do</u>	Sails <u>do</u> <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>2 1/2</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete &amp; Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>fine</u> When put on <u>1855</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

No. now in good condition fit for the safe conveyance of Dry and  
Perishable Cargoes and in my opinion may be Classed A. 1.  
The Owner declining Special Survey until the zinc sheathing requires  
stripping

Committee's Minute 4th February 1859

Character assigned A. 1

Wm. Robertson

Certificate (if required) Free

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 185\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Certificate (if required).

Lloyd's Register  
Foundation

GLS142-0267