

ANNUAL SURVEYS.

1572

Rec 23/6/59

No. 1572 Survey held at Glasgow Date 20th June 1859
 on the Ship Canada Master John de? Ruffie
 Tonnage 330 Built at Greenock When built 1831
 By whom built Steel Owners Allan & Co
 Port belonging to Greenock Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Afloat


JR

Last Survey, No. 1391 Port of Glasgow Classed 10 *R.A. S.S. 53
 Restab — 57

The present Condition of the		
Decks <u>Where seen Good</u>	Treenails <u>Where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do do</u>	Breasthooks and Stenson <u>do do</u>	Pumps <u>4 do</u>
Comings <u>do do</u>	Transoms, Pointers, and Crutches <u>do do</u>	Boats <u>3 do</u>
Upper Deck Beams & Fastenings <u>do do</u>	Timbers of the Frame <u>do do</u>	Masts, Yards, &c. <u>Complete & Good</u>
Lower Deck Beams & Fastenings <u>do do</u>	Keelsons <u>do do</u>	Sails <u>do do</u>
Planksheers <u>do do</u>	Clamps and Shelves <u>do do</u>	Anchors No. of <u>3 B. 1 other 1/2</u>
Sheerstrakes <u>do do</u>	Ceiling <u>do do</u>	Cables <u>Complete & Good</u>
Topsides <u>do do</u>	Rudder <u>do do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do do</u>	Copper <u>Yellow Metal</u> When put on <u>Decr 58</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do do</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good, Where seen
At Crown in December last, Bottom stripped, Caulked and Sheathed with Yellow Metal;
At present appears in good & efficient
Condition fit for the safe Conveyance of dry and perishable Cargoes


Committee's Minute 24th June 1859 to and from all parts of the Board and
 Character assigned R, 1 asterisk to continue as Claquee


 Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____		
The present Condition of the		
Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____		

Committee's Minute _____ 18____
 Character assigned _____



GLS142-0298