

ANNUAL SURVEYS.

1587

No. 1587 Survey held at Glasgow Date 12th August 1859
 on the Ship Caledonia Master M. Hamilton
 Tonnage 383 Built at Greenock When built 1841
 By whom built 238 Owners Allan & Co.
 Port belonging to Greenock Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Patent Slip & Afloat

Last Survey, No. 1538 Port of Glasgow Classed Rate 55, 7 A.T.

The present Condition of the

Decks <u>Good</u>	Treenails <u>Apparently Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>Not Seen</u>	Pumps <u>Complete & Good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Where Seen Good</u>	Sails <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do do</u>	Anchors No. of <u>3 B. 1 Stem Wedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u>	Rudder <u>Good</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>1839</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways New

New False Keel; Caulked over all and sheathed the Bottom with Yellow Metal over felt

is now in good and efficient condition and may be continued as

Committee's Minute

16th August 1859

Classed

Character assigned

Rate 7 1/2

Record M.L.R.

Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute

18

Character assigned

Certificate (if required).



© 2019

Lloyd's Register Foundation

GLS142-0312