

ANNUAL SURVEYS.

1875
Rev 8/3/62

No. 1875 Survey held at Glasgow Date 19th February 1862
on the Shunter Sapphire Master John Campbell
Tonnage 177 Built at Greenock When built 1846
By whom built ✓ Owners Mr Arthur Butcher
Port belonging to Glasgow Destined Voyage Liverpool & back
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1805 Port of Glasgow

Classed 10 Δ 1 Red
C 3 11

The present Condition of the

Decks <u>Good</u>	Treenails <u>Where seen, Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u> <u>do</u>	Pumps <u>2</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u> <u>do</u>	Boats <u>2</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u> <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u> <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do</u> <u>do</u>	Anchors No. of <u>2 1/2</u> <u>1</u> <u>Star</u> <u>Wedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u> <u>do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u>	Rudder <u>do</u> <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>Single</u> When put on <u>Bottom</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>Where seen do</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good Where seen

Is in good Condition fit for the safe conveyance of dry perishable
Cargoes to & from all parts of the World & may continue as Clashed

Committee's Minute 4th March 1862

Character assigned Δ 1 in Red W

B. D. Hutton

Certificate (if required)

No. 1875 Survey held at Glasgow Date 18th February 1862
on the Barge "Emperor" Master Arthur P. Allan
Tonnage 438 Built at Dumbarton When built 1849
By whom built 4970, Mr. Millar & Co Owners Duncan Finlayson
Port belonging to Glasgow Destined Voyage Dumfries
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1596 Port of Glasgow

Classed 10 Δ 1
Cont 39 3 59

The present Condition of the

Decks <u>Where seen Good</u>	Treenails <u>Where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u> <u>do</u>	Breasthooks and Stemson <u>do</u> <u>do</u>	Pumps <u>4</u> <u>do</u>
Comings <u>do</u> <u>do</u>	Transoms, Pointers, and Crutches <u>do</u> <u>do</u>	Boats <u>3</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u> <u>do</u>	Timbers of the Frame <u>do</u> <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u> <u>do</u>	Keelsons <u>do</u> <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u> <u>do</u>	Clamps and Shelves <u>do</u> <u>do</u>	Anchors No. of <u>3 1/2</u> <u>1</u> <u>Star</u> <u>Wedge</u>
Sheerstrakes <u>do</u> <u>do</u>	Ceiling <u>do</u> <u>do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u> <u>do</u>	Rudder <u>do</u> <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u> <u>do</u>	Copper <u>2 Metal</u> When put on <u>1859</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>do</u> <u>do</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Where seen, Good

Is in good Condition where seen and may continue as Clashed

Committee's Minute 4th March 1862

Character assigned Cont 3 Δ 1 W

B. D. Hutton

Certificate (if required)

See for Charge of Owner

9900-34579