

# ANNUAL SURVEYS.

1991

Rev 15/1/63

*[Signature]*

No. 1991 Survey held at Glasgow Date 27th January 1883  
 on the Barge John Gray Master A. Calder  
 Tonnage 479 Built at Greenock When built 1842  
 By whom built \_\_\_\_\_ Owners James Spiers  
 Port belonging to Glasgow Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1584 Port of Glasgow Classed 9 A. 1. 19  
Net 58.6 Tons

The present Condition of the

Decks <u>Good</u>	Treenails <u>As true been Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B. 1 Sym Wedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>9 Metal</u> When put on <u>1862</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>As true been</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Windlass Shipped, new Purchase fitted, Reined & Hung  
By Bill produced, the Copper has been l. shed from keel to Wales and sheathed  
with Yellow Metal on felt to 16 feet At St. Thomas in October 1862  
is in good Condition and Eligible to remain as Classed

Committee's Minute 16th January 1883

Character assigned

Best 1st

record 4M

*[Signature]*

Certificate (if required)

Survey Fee £1.1

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 185\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
Foundation

Certificate (if required).

GLS143-0149