

# ANNUAL SURVEYS.

2245

No. 2245 Survey held at Glasgow Date 28th September 1864  
 on the Brig, Lisbon Master William Cook  
 Tonnage 221 Built at Austwick When built 1852  
 By whom built John Mitchell Owners John Mitchell  
 Port belonging to Glasgow Destined Voyage Lisbon  
 If Surveyed Afloat or in Dry Dock Barclay Curle & Co. Patent Slip

Last Survey, No. 1853 Port of Glasgow Classed 12.61 omitted

The present Condition of the

Decks <u>When seen Good</u>	Treenails <u>When seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>at the Openings</u> <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Do Do at other places <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>3 1/2 1 1/2 1 1/2</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>Complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>Plated</u> When put on <u>1861</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Ship in good Condition Eligible in my opinion to be Classed A. 1.

Committee's Minute 14th October 1864

Character assigned A. 1

A. C. Darling

Clipping See  
 Certificate (if required)  
Survey 0-10-6

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u> _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
 Foundation

Certificate (if required).

GLS143-0317